

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



UR.

Michael O. Leavitt Governor Lowell P. Braxton

Division Director

PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

1594 West North Temple, Suite 1210

Partial: XXX Complete: Exploration: Inspection Date & Time: 9/17/99 / 10:30a.m.-3:00p.m.

Date of Last Inspection: 8/10/99

Mine Name: Hidden Valley Mine County: Emery Permit Number: ACT/015/007						
Permittee and/or Operator's Name: Consolidation Coal Company						
Business Address: P.O. Box 566, Sesser, Illinois 62884						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Steve Behling						
State Officials(s): Bill Malencik Federal Official(s): None						
Weather Conditions: Partly Cloudy, 70's						
Existing Acreage: Permitted- <u>950</u> Disturbed- <u>7</u> Regraded- <u>Seeded-</u> Bonded- <u>7</u>						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_Liability_1986_Year)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

<u>Instructions</u>

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3. 4.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL HYDROLOGIC BALANCE:	EVALUATED [XX] []	<u>N/A</u> 	COMMENTS L1 L1	NOV/ENI
a. b. c. d. e. 5. 6. 7. 8. 9.	DIVERSIONS SEDIMENT PONDS AND IMPOUNDMENTS OTHER SEDIMENT CONTROL MEASURES WATER MONITORING EFFLUENT LIMITATIONS EXPLOSIVES DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE PROTECTION OF FISH, WILDLIFE AND	[XX] [XX] [XX] [] [] [XX] [XX]			
10. 11. 12. 13. 14. 15.	RELATED ENVIRONMENTAL VALUES SLIDES AND OTHER DAMAGE CONTEMPORANEOUS RECLAMATION BACKFILLING AND GRADING REVEGETATION SUBSIDENCE CONTROL CESSATION OF OPERATIONS ROADS:				
a. b. 17. 18. 19. 20.	CONSTRUCTION/MAINTENANCE/SURFACING DRAINAGE CONTROLS OTHER TRANSPORTATION FACILITIES SUPPORT FACILITIES/UTILITY INSTALLATIONS AVS CHECK (4th Quarter-April, May, June) (date) AIR QUALITY PERMIT BONDING & INSURANCE				

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>3</u>

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 9/17/99

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

A partial complete inspection of the Hidden Valley reclaimed mine site was conducted by the undersigned.

SUMMARY

No violations were issued. The environmental control measures appear to meet the coal rule performance standards.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were stable and showed no evidence of recent runoff. The diversion above the "A" seam maintained this past summer, meets performance standards. Some fine material from the escarpment is being deposited in the diversion, but doesn't constitute a concern at this point in time.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The MRP requires water monitoring at high and low flow. The sampling on Ivie Creek above and below the mine are to be taken in May and September. The last sampling was taken September 16, 1999.

8. NONCOAL WASTE

The noncoal waste on the surface is not a problem. The exception is at the end of the county road. However, no noncoal waste, pop cans, etc. were observed during the instant inspection.

12. BACKFILLING AND GRADING

As previously documented in prior inspection reports, the "B" seam was regraded in 1997.

13. REVEGETATION

Seedlings we observed from last years rehabilitation efforts. The seedlings are most numerous in the regraded depression areas. See Susan White's technical report that is made an official part of the instant inspection.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 9/17/99

(Comments are Numbered to Correspond with Topics Listed Above)

21. BONDING AND INSURANCE

Insurance expires 11/5/99. The surety bond is on records for \$90,758.00 and no bond release has been approved by the Division.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: <u>Tim Kirschbaum (Consol)</u> <u>Henry Austin (OSM)</u>
Given to: Pam Grubaugh-Littig (DOGM) Filed to: Price Field Office

Given to: Pam Grubaugh-Littig (DOGM)
Date: September 19, 1999

Inspector's Signature: Malancie #26

Wm. J. Malencik